Unit 124

The lifters were making a knocking/tapping sound within the engine. Upon receiving authorization to replace the camshaft and lifters we tore the engine down and removed the camshaft. After removing the camshaft we noticed the camshaft bearing on the engine block itself has severe scoring on it. If we replace just the camshaft and lifters the engine may fail prematurely due to the bearing scoring. This bearing is part of the block assembly and cannot be replaced. The only option in this case is to replace the engine.

The warranty on the engine is 3 years or 100,000 miles, whichever comes first.

PART NAME ENGINE LONG BLOCK OIL FILTER OIL COOLANT SPARK PLUGS	PART NUMBER 68276264AA 4884899AC 4761872PB 68048953AB SPLZFR5C11	PRICE \$5200.00 \$6.68 \$3.10 \$18.56 \$4.56	QTY 1 1 7 1 16	TOTAL \$5200.00 \$6.68 \$21.70 \$18.56 \$72.96
LABOR		\$90.00	22.0	\$1980.00
TOTAL PARTS AND LABOR				<u>\$7299.90</u>

David Rudie

Chrysler Service Advisor

Ron Carter

P.O. Box 459

Alvin, TX 77512

Service: 281.331.8111

Direct: 281.388.8582