

SUMMARY OF VEHICLES IMPACTED BY HURRICANE HARVEY (As of 9/21/17)

FLOODED						
UNIT#	YEAR	DESCRIPTION	VIN#	REPLACEMENT PRICE (estimate)	DEPARTMENT	NOTES
10	2011	Tahoe	1GNLC2E07BR226101	64,000	Fire	Was used during the storm. Couldn't make it back to PSB. Norman Frede - authorized tear down only
104	2014	Ford Explorer Interceptor	1FM5K8AR1EGB85505	65,000	Police	Patrol - PAV parked in driveway at Officer's house (Subdivision behind Mcree Ford)
109	2017	Ford Explorer Interceptor	1FM5K8ATXHGB65379	65,000	Police	Traffic - PAV parked in driveway at Officer's house (off 517 in Dickinson) (ADJUSTER COMING BACK OUT TOMORROW TO DETERMINE TOTAL LOSS OR REPAIR) Bayway pending quote
110	2017	Ford Explorer Interceptor	1FM5K8AT7HGA36693	65,000	Police	Patrol - PAV parked in driveway at Officer's house (Dove Meadows subdivision) Bayway pending quote
112	2013	Ford Explorer Interceptor	1FM5K8AR4DGC15787	65,000	Police	Patrol - Parked at McRee Ford (C0 testing)
116	2017	Ford Explorer Interceptor	1FM5K8AT5HGA24395	65,000	Police	Patrol - PAV parked in driveway at Officer's house (The Meadows subdivision) Total loss
141	2014	Ford Explorer Interceptor	1FM5K8AR5EGB85491	65,000	Police	Patrol - PAV parked in driveway at Officer's house (Friendswood)
146	2013	Ford Explorer Interceptor	1FM5K8AR6DGC15791	65,000	Police	Patrol - On Duty - Median of FM 646/Misty Bay
159	2013	Ford Explorer Interceptor	1FM5K8AR3DGC63023	65,000	Police	Patrol - PAV parked in driveway at Officer's house (LaMarque)
162	2014	Ford Explorer Interceptor	1FM5K8AR6EGB85502	65,000	Police	Patrol - PAV parked in driveway at Officer's house (Dove Meadows subdivision) Total loss
210	2015	Ford Explorer Interceptor	1FM5K8AR1FGC08248	65,000	Police	Patrol - Parked at McRee Ford (C0 testing)
222	2016	Ford Explorer Interceptor	1FM5K8AT1GGB74079	65,000	Police	CID - PAV parked in driveway at Officer's house (Magnolia Estates subdivision)
222	2016	Ford Fusion	3FA6POG73GR345287	25,116	Police	CID - PAV parked in driveway at Officer's house (Bay Colony subdivision) Total loss
314	2009	Toyota Camry	4T1BB46K59U097409	25,116	Police	CID - PAV parked in driveway at Officer's house
237	2006	F250 Truck	1FTSX21P06ED27604	39,000	EMS	Vehicle was flooded at Hwy 96 and FM 270 while responding to a call
535	2002	Tahoe	1GNEK13Z22J308159	26,000	Engineering	Parked at employee's residence. SE corner of the West Deats Road and Hughes Lane. Bayou Village Apartment Complex
603	2013	F150 Truck	1FTEX1EM3DFB54322	25,000	Line Repair	Parked at employee's residence. 804 Rosewood Dr., Dickinson Total loss
649	2017	F250 Truck	1FT7X2A66HEC48566	28,000	Wastewater	Flooded trying to reach lift station, 5401 Brittany Bay, Westover Park. Bayway being repaired
759	2013	F150 Truck	1FTEX1CM8DFB54321	25,000	Facilities	Employee trying to get to Hometown Heroes on Hwy 96 and flooded. Total loss
820	1999	Dump Truck	1GBM7H1C9XJ100787	70,000	Streets	Flooded during high water rescue and/or transport (Bay Colony) Monument Chevrolet pending quote

829	1999	Dump Truck	1GBM7H1C1XJ100721	70,000	Streets	Flooded during high water rescue and/or transport (Clear Lake Village) Monument Chevrolet pending quote
863	2009	Dump Truck	3FRXF75A29V112085	70,000	Streets	Flooded during high water rescue and/or transport (Clear Lake Village) Bayou City Ford or Cummins for pending quote
WATER DAMAGED						
1	2003	F250 Truck	1FTNW21P53ED09630	Unknown	Fire	<i>Emergency Response; Electrical issue / no power to console or MDT; awaiting inspection</i>
4	1999	F350 Truck	1FTSW31FXXED76519	Unknown	Fire	<i>Emergency Response; Possible water in fuel; awaiting inspection</i>
5	2008	Booster Truck	1FDWF31RX8EC93391	Unknown	Fire	<i>Awaiting insurance adjuster inspection</i>
6	2009	Tahoe	1GNEC03039R202436	Unknown	Fire	<i>Emergency Response; Water in back door and bottom; awaiting inspection</i>
12	2011	Tahoe	1GNLC2E04BR346244	Unknown	Fire	<i>Emergency Response; Water leak in roof; awaiting inspection</i>
16	1993	Pumper Truck	4P1CT02D6PA000567	Unknown	Fire	pending on quotes from Siddons Martin for repairs
18	1993	Pumper Truck	4P1CT02D4PA000681	Unknown	Fire	pending on quotes from Siddons Martin for repairs
21	2011	Pumper Truck	4S7AT2D91BC072843	Unknown	Fire	<i>Emergency Response; Water in front of wheel bearing oil hubs; awaiting inspection</i>
41	1994	Snorkel Truck	4P1CT02D7RA000192	Unknown	Fire	pending on quotes from Siddons Martin for repairs
82	2003	Crown Victoria	2FAFP71WX3X221845	Unknown	IT	<i>Awaiting insurance adjuster inspection</i>
105	2011	Charger	2B3CL1CT5BH551931	Unknown	Police	Repaired by Barn and returned back to service. Waiting on total cost.
136	2010	Charger	2B3CA4CTXAH258225	Unknown	Police	Repaired by Barn and returned back to service. Waiting on total cost.
151	2017	Interceptor Explorer	1FM5K8AT6HGB65380	Unknown	Police	Repaired by Barn and returned back to service. Waiting on total cost.
170	2011	Charger	2B3CL1CT7BH551929	Unknown	Police	Repaired by Barn and returned back to service. Waiting on total cost.
610	2007	Dump Truck	1HTWGAAR18J645791	Unknown	Line Repair	Gass Automotive req#1171762
7505	2002	Crown Victoria	2FAFP71W62X125385	Unknown	VM/Pool Car	<i>Awaiting insurance adjuster inspection</i>