WORK CHANGE DIRECTIVE (WCD) NO. 3

| PROJECT: | ED1503 – Park Avenue from Wil | lkins Street to Eas | st Main S | Stree | t | |
|--|---|------------------------------|-----------|---------|--|---|
| OWNER: | City of League City | | | | | |
| ENGINEER: | Huitt-Zollars | | | | | |
| CONTRACTOR: | Conrad Construction Co. LTD | | | | | |
| You are directed to mak | e the following changes in the Con | ntract: | | | | |
| DESCRIPTION AND R | EASON FOR THIS WCD: | | | | | |
| wiring; and removing a | with a service relocation/modificated replacing driveway pavement found in the plans was not to TNN | for an open cut ti | ench. T | | | |
| DESCRIBE CONTRAC | T PRICE (INCREASE/DECREAS | SE) CHANGE FO | R THIS | s wc | D: | |
| This change order will in | ncrease the contract price by \$26,1 | 29.14 for materia | l, labor, | and o | overhead. | |
| ATTACHMENTS: | | | | | | |
| | CHANGES IN CONT | TRACT PRICE | | | | |
| ORIGINAL CONTRAC | | \$ 1,050,418.00 | | | | |
| NET CHANGES FROM CHANGE BY THIS WO | | \$ 37,742.19 \$ 26,129.14 | | | | |
| | ITH ALL APPROVED WCDS: | \$ 1,114,289.33 | | | | |
| | CHANGES OR EXTENSIONS | S IN CONTRACT | TIME | | | |
| ORIGINAL CONTRAC INCREASED TIME FR INCREASED TIME FR REVISED CONTRACT | OM PREVIOUS WCDS: OM THIS WCD: | | | 13 5 | Calendar Days Calendar Days Calendar Days Calendar Days | |
| SUBMITTED BY: | Brian Conrad, Conrad Constr | mation | DATE: | | | _ |
| | Bilan Colliau, Colliau Collisti | TUCHOII | | | | |
| RECOMMENDED BY: | Keith Davis, Huitt-Zollars | | DATE: | | | - |
| OWNER APPROVAL B | sy: | | DATE: | | | |
| | John Baumgartner, City Man | nager | ~····· | | | - |

CONRAD CONSTRUCTION CO., LTD. P.O. BOX 841134 HOUSTON, TEXAS 77284

Proposal

Date:11/5/19

RFP: 9

Owner: City of League City

Project: Park Ave.

Ref. RFI

Description: Service Relocation/Modification, Additional conduit and wiring,

Remove and replace driveway pavement for open cut conduit trench

Materials:

| Item | Item Qty Unit Unit Price | | Init Price | Unit Total | |
|---|---|----|------------|------------|----------------|
| Concrete driveway repair for open cut conduit | 1 | LS | \$ | 1,250.00 | \$ 1,250.00 |
| Base material under driveway repair | 1 | LS | \$ | 400.00 | \$ 400.00 |
| | | | \$ | - | \$ - |
| Total Material | *************************************** | | | | \$ 1,650.00 |

Labor:

| Name and/or Position | Qty | Unit | (| Init Price | Unit Total | | |
|---------------------------------------|-----|------|----|------------|------------|----------|--|
| ility Crew - Foreman/operators/labors | 1 | day | \$ | 2,250.00 | \$ | 2,250.00 | |
| | | | \$ | - | \$ | | |
| Total Labor | | | | | \$ | 2,250.00 | |

Equipment:

| Item | Qty | Unit | Unit Price | Unit Total |
|-----------------------|-----|---|---|----------------|
| Equipment - excavator | 1 | day | \$ 1,000.00 | \$ 1,000.00 |
| dump truck | 1 | day | \$ 450.00 | \$ 450.00 |
| Total equipment | | *************************************** | *************************************** | \$ 1,450.00 |

Subcontractor - Pfeiffer & Son

| Item | Qty | Qty Unit | | Unit Price | | Unit Total | |
|-----------------------------------|------|-----------|----|------------|----|------------|--|
| Additional 1-1/2" conduit | 415 | LF | \$ | 16.06 | \$ | 6,664.90 | |
| Additional #10 Wire | 3000 | LF | \$ | 0.86 | \$ | 2,580.00 | |
| Additional #8 Wire | 2000 | LF | \$ | 1.55 | \$ | 3,100.00 | |
| Additional #6 Wire | 4000 | LF | \$ | 1.60 | \$ | 6,400.00 | |
| Service Relocation / Modification | 1 | L5 | \$ | 2,800.00 | \$ | 2,800.00 | |
| Total equipment | \$ | 21,544.90 | | | | | |


| Total Equipment, Labor, Material, Misc. |
|---|
| OH&P 15% |
| Total |
| Time Request |

\$ 26,894.90 \$ 4,034.24 \$ 30,929.14 5 Days

** These changes delete pay items #86 / #87 from contract for a deduct of \$4800

\$26,129.14 NET INCREASE

Brian Conrad Vice President



Pfeiffer and Son is proposing to install (3) 1 1/2" PVC conduits from the new service location to:

* Service-electrical panel to PB #15 where the circuits will split off for lighting and receptacles as shown above
* Service-electrical panel to location where (2) 4" PVC sleeves were previously installed. Using sleeving, push (2)
1 1/2" PVC conduit across roadway and tie into irrigation controller with 1 conduit, and tie into PB#11 with the other 1 1/2" PVC conduit. Circuits will split off for lighting, receptacles, and irrigation controller as shown above
*Calculations for lighting are based off of using 240V power with 2 circuits (5 on each)

*Calculations for receptacles are based off the original drawing showing circuits of #6 wire.

*Pfeiffer and Son has Broken out the GFI pole mounted receptacle into a separate circuit of #6 wires.

Electrical & Telecommunication Contractors

Bid Date: November 6, 2018 (revised 11/1/19)

Project Name: Park Avenue

| SECTION I GENERAL | | original revised | | | | ori | ginal | revised | | | |
|-------------------|---|------------------|------|---|-------------|-----|----------|---------|-----------|--|------|
| ITEM# | DESCRIPTION | UNIT | QTY. | | UNIT \$ TOT | | \$ TOTAL | | T\$ TOTAL | | OTAL |
| | Remove and Reinstall Loop Detectors and Loop Lead-in Cables Connect to Existing Pullbox | LS | 1 | 1 | \$ 2,500.00 | \$ | 2,500.00 | \$ | 2,500.00 | | |
| | | | | | SUBTOTAL | \$ | 2,500.00 | \$ | 2,500.00 | | |

| SECTIO | N VIII ELECTRICAL | | original | revised | | original | revised | |
|--------|-----------------------------------|------|----------|---------|-------------|---------------|---------------|--|
| ITEM# | DESCRIPTION | UNIT | QTY. | QTY. | UNIT \$ | TOTAL | TOTAL | |
| 76 | Pull Box | EA | 17 | 17 | \$ 980.00 | \$ 16,660.00 | \$ 16,660.00 | |
| 77 | Receptacle | EA | 14 | 14 | \$ 220.00 | \$ 3,080.00 | \$ 3,080.00 | |
| 78 | Pedestrian Light Pole and Fixture | EA | 10 | 10 | \$ 7,750.00 | \$ 77,500.00 | \$ 77,500.00 | |
| 79 | 2" Conduit | LF | 385 | 385 | \$ 16.86 | \$ 6,491.10 | \$ 6,491.10 | |
| 80 | 1-1/2" Conduit | LF | 229 | 644 | \$ 16.06 | \$ 3,677.74 | \$ 10,342.64 | |
| 81 | 1" Conduit | LF | 457 | 457 | \$ 14.85 | \$ 6,786.45 | \$ 6,786.45 | |
| 82 | 1/2" Conduit | LF | 528 | 528 | \$ 9.08 | \$ 4,794.24 | \$ 4,794.24 | |
| 83 | #10 Wire | LF | 4,100 | 7100 | \$ 0.86 | \$ 3,526.00 | \$ 6,106.00 | |
| 84 | #8 Wire | LF | 680 | 2680 | \$ 1.55 | \$ 1,054.00 | \$ 4,154.00 | |
| 85 | #6 Wire | LF | 2,100 | 6100 | \$ 1.60 | \$ 3,360.00 | \$ 9,760.00 | |
| 86 | #4 Wire | LF | 900 | 0 | \$ 1.70 | \$ 1,530.00 | \$ - | |
| 87 | #3 Wire | LF | 1,000 | 0 | \$ 2.61 | \$ 2,610.00 | \$ - | |
| Adder | Service Relocation/Modification | LS | 0 | 1 | \$ 2,800.00 | \$ - | \$ 2,800.00 | |
| | | | | | SUBTOTAL | \$ 131,069.53 | \$ 148,474.43 | |
| | | | | | TOTAL | \$ 133,569.53 | | |
| | | | | | | | | |

^{*}Revised pricing is based upon approval of drawings submitted by Pfeiffer and Son.

Total With Revisions

To avoid confusion, we offer the following clarifications:

- 1. Engineering and staking by G.C.
- 2. Sales tax is not included in this gutoe.
- 3. Bond is not included; our rate is 2.5%.
- 4. Traffic control by G.C. (Including police officers, if required.)
- 5. Existing foundations broken down and removed by GC.
- 6. G.C to saw cut, breakout, remove and repair concrete rip rap and or sidewalks/ramps for conduit, boxes, and light pole foundations.
- 7. G.C. to remove and dispose of spoils from foundations and conduit installations.
- 8. Removal, relocation, or temporary street lighting is excluded from our quote.

PLEASE SEE NEXT PAGE FOR CLARIFICATIONS CONTINUED

\$ 150,974.43

^{*}Pricing is based on Conrad Construction sawcutting across necessary driveways, and digging out to expose existing 4" sleeves to be used to get (2) 1 1/2" conduits across the street.

Electrical & Telecommunication Contractors

- Pfeiffer & Son, Ltd. will provide insurance coverage in accordance with our standards.
 Additional coverage specifically required by the contractor may necessitate additional premium charges.
- 10. Our quote includes tying into existing 50kva transformer for power.
- 11. The existing C-Channel services will be utilized for powering up the new lights and receptacles. The electrical panel will have to be replaced in order to accommodate the new contactor, photocell and circuits.
- 12. Pfeiffer and Son will provide a new 1 1/2 conduit with a power circuit to power up the irrigation controller.
- 13. Item #9 (loop detectors) is for the installation of (1) 6x40 loop with lead in cable to existing pull box. If any additional loops or pull boxes are needed, this quote will need to be revised.

We appreciate this opportunity to quote on this project. If you have any questions or need additional clarifications, please call us at (281) 471-4222.

Sincerely,

Nick Riley

PHONE-(281) 471-4222 * FAX-(281) 471-6856 P.O. BOX 1116 * 116 N. 16TH. ST.

LA PORTE, TEXAS 77572

REGULATED BY THE TEXAS DEPARTMENT OF LICENSING AND REGULATION CONTRACTOR'S LICENSE #18259

P.O. BOX 12157 * AUSTIN, TX 78711

(800) 803-9209 * (512) 463-6599 * www.license.state.tx.us/complaints
ADOPTED ADMINISTRATIVE RULES: 73.51 © ELECTRICAL CONTRACTORS' RESPONSIBILITIES