

MEMORANDUM

To:

Purchasing Department

From:

Ramiro Ochoa, Wastewater Superintendent

CC:

Jody Hooks, Public Works Director

Tommy Arredondo, Public Works Utility Manager

Date:

8/26/2024

Re:

Dallas Salmon WWTP - Re-Lift Pump #3 Repair - Urgent Repair

Comments:

The Wastewater Department is seeking approval for Urgent Repair of the #3 Re-Lift Pump located at the Dallas Salmon Wastewater Treatment Plant. There are significant repairs needed for this pump due to failure of major components. Historically during major rain events (tropical storms or hurricanes) the Dallas Salmon Re-lift station utilizes all four pumps to accommodate the increased flow during these events. Utilizing all four of the Dallas Salmon Re-lift station pumps is critical to maintain flow to the disc filters and out of the plant. The Dallas Salmon Wastewater Treatment Facility is Texas Commission on Environmental Quality (TCEQ) Category "A-Major" wastewater treatment facility. It is imperative to repair Re-lift pump #3 promptly to keep the Re-lift station operating to meet regulatory compliance regulations. Pump Solutions Inc. is the authorized Sole Source facility that will complete the repairs of this pump. Total cost is \$61,178.00 and funds are available in account 1027500-52620.

Please feel free to reach out to me with any questions,

Ramiro Ochoa



18594 US Hwy 59 New Caney, Texas 77357 Phone: 281-399-9400

Fax: 281-399-9401 Cell: 346-731-1684

THIS TRANSMITTAL CONSISTS OF 1 PAGE(S) INCLUDING THIS PAGE.

TO: Jimmy Walker @ City of League City

FROM: Mike Crawford Bid DATE: 8/26/24

RE: Dallas Salmon WWTP Propeller Pumps P-1

PSI Job # 2604

Pump Solutions Inc. is pleased to offer the following parts for the subject project:

SUCTION BELL BEARING

BEARING RETAINER

THRUST RING FOR PROPELLER

PROPELLER KEY

SAND CAP

PROPELLER RING

DIFFUSER CASE RING

DIFFUSER BEARING HOUSING

BEARING "CARE"

BOWL SHAFT

COVER PIPE (INTERM)

COVER PIPE (INTERM FOR SPIDER)

COVER PIPE (UPPER)

INTERMEDIATE BEARING HOUSING

BEARING "CARD"

PACKING BOX

BEARING "CARD"

O-RING

PACKING GLAND

LINE SHAFT

UPPER SHAFT

SHAFT COUPLING

GIB KEY

COUPLING KEY SPECIAL

SUCTION CAN O-RING

SSCP 5/16"-18UNCX5/8"LG

> Repair on a Patterson 18X20 AVF Vertical Turbine pump.

Findings:

Catastrophic failure. Multiple major components have failed.

Shafts are worn, lubricating tubes have stripped threads they have been spinning as one unit with the shafting, this has caused damage to the stuffing box and all bearings, Propeller thrust-ring and sand cap.

Corrective action:

Replace all lubricating tubes, shafting, bearings stuffing box and all other parts listed above.

Installation W/customer providing crane\$ 3,600.00

TOTAL PRICE.....\$ 61,178.00 (6-8 week lead time on parts)

PLEASE SIGN AND SEND BACK TO PROCESS THIS QUOTE.

Thank you for your consideration of the proposed quote.

Mike Crawford



Date:

July 18, 2024

TO:

Whom it may concern

SUBJECT:

Market Representation

TERRITORY:

The State of Texas

PRODUCT:

MUNICIPAL WATER AND WASTEWATER PUMPS

This letter is to confirm the following company and their agents are the sole proprietary Sales and Service Agents for Patterson Pump Company in the above referenced territory for pumps and pump parts sales in the Municipal Water and Wastewater Market.

PATTERSON REPRESENTATIVE:

Pump Solutions, Inc.

18594 US HIGHWAY 59 NEW CANEY TX 77357 (817) 684-0900 Main (817) 684-0905 Fax

And such other offices Pump Solutions, Inc. may deem appropriate to utilize in serving our Municipal Water and Wastewater Customers.

Please contact me at Patterson Pump Company if there are any questions concerning this representative organization and their responsibilities.

Kyle Smith

Custom Pump Regional Sales

Manager Patterson Pump Company

706-297-2963

Kyle.Smith@pattersonpumps.com

cc Brooke Stonecypher, Custom Pump Regional Sales Manager

cc Mike Ellers, Service-Parts Sales Manager

Patterson Pump Company. A Gorman-Rupp Company P.O. Box 790. 2129 Ayersville Road. Toccoa, Georgia 30577 Phone: (706) 886-2101